

Part-II

(To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on 18 Sept 2019 and have visually inspected it from all angles of safety and I found it fit for normal use as School building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or eaves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safely occupied for normal use upto 31.3.2020  
(indicate year upto which it can be used).

  
Sub Divisional Engineer  
Constn. Sub Division No. 2,  
P.W.D. B&R, Ludhiana.  


ਜੀ.ਆਰ. ਨੰ: 19091


ਮਿਤੀ 06.09.2019

ਨੰ: 178-79

ਮਿਤੀ 24.9.2019

✓ ਮੂਲ ਰੂਪ ਵਿਚ ਪ੍ਰਿੰਸੀਪਲ, ਸੁਆਮੀ ਗੰਗਾ ਗਿਰੀ ਜਨਤਾ ਗਰਲਜ ਕਾਲਜ ਰਾਏਕੋਟ ਜਿਲਾ ਲੁਧਿਆਣਾ ਨੂੰ ਆਪ ਦੇ ਪੱਤਰ ਮਿਤੀ 28.08.2019 ਦੇ ਸਬੰਧ ਵਿਚ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਅਪ ਟੂ 31.03.2020 ਤੱਕ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

2. ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ:1, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

  
ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,  
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:2  
ਲੋ:ਨਿ:ਵਿ: ਭ ਤੇ ਮ ਸਾਖਾ,  
ਲੁਧਿਆਣਾ।